CARFAX Veh	icle H	us \$39.99 Us \$39.99
2006 SAAB 9-3 VIN: YS3FD79Y966005518	<b>~</b>	No accidents reported to CARFAX
CONVERTIBLE 2.0L I4 F SOHC GASOLINE FRONT WHEEL DRIVE	✓	No damage reported to CARFAX
	*	2 Previous owners
	Ŵ	At least 1 open recall
		Types of owners: Personal lease, Personal
	79128	55,306 Last reported odometer

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/18/20 at 2:29:15 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

<b>CARFAX</b> Ownership History The number of owners is estimated	🚨 Owner 1	💄 Owner 2
Year purchased	2006	2008
Type of owner	Personal lease	Personal
Estimated length of ownership	2 yrs. 3 mo.	6 months
Owned in the following states/provinces	Wisconsin	See Details
Estimated miles driven per year	7,363/yr	
Last reported odometer reading	17,036	55,306

CARFAX Title History CARFAX guarantees the information in this section	💄 Owner 1	🔓 Owner 2
Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	Guaranteed No Problem	Guaranteed No Problem
Not Actual Mileage   Exceeds Mechanical Limits	Guaranteed No Problem	Guaranteed No Problem



**GUARANTEED** - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back.

## Register | View Terms | View Certificate

<b>CARFAX</b> Additional History Not all accidents / issues are reported to CARFAX	💄 Owner 1	🔓 Owner 2
Total Loss	No Issues	No Issues
No total loss reported to CARFAX.	Reported	Reported
Structural Damage	No Issues	No Issues
No structural damage reported to CARFAX.	Reported	Reported
Airbag Deployment	No Issues	No Issues
No airbag deployment reported to CARFAX.	Reported	Reported
Odometer Check	No Issues	No Issues
No indication of an odometer rollback.	Indicated	Indicated
Accident / Damage	No Issues	No Issues
No accidents or damage reported to CARFAX.	Reported	Reported
Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized <u>Saab dealer</u> to obtain more information about this recall.	No Recalls Reported	Recall Reported
Basic Warranty <u>Original warranty</u> estimated to have expired.	Warranty Expired	Warranty Expired

# **CARFAX** Detailed History

Owner Purchas 2006	-	<b>Low mileage!</b> This owner drove less than the industry average of 15,000 miles per year.	Personal Lease Vehicle 7,363 mi/yr
Date	Mileage	Source	Comments
12/08/200	5	US Customs	<b>Vehicle exported from</b> -Belgium and imported to -Newark, NJ
03/18/200	6 150	Wisconsin Motor Vehicle Dept. Milwaukee, WI	Odometer reading reported -Titled or registered as personal lease vehicle

2/1	8/2020
- 1	0,2020

CARFAX Vehicle History Report for this 2006 SAAB 9-3: YS3FD79Y966005518

03/20/2006	Wisconsin Motor Vehicle Dept. Milwaukee, WI Title #06079C0750200	<b>Title issued or updated</b> -Registration issued or renewed -First owner reported -Loan or lien reported -Vehicle color noted as Yellow
03/12/2007	Wisconsin Motor Vehicle Dept. Milwaukee, WI	<b>Registration issued or renewed</b> -Vehicle color noted as Yellow
03/18/2008	Wisconsin Motor Vehicle Dept. Milwaukee, WI	<b>Registration issued or renewed</b> -Vehicle color noted as Yellow
07/02/2008 17,036	Auto Auction	Vehicle sold
		Millions of used vehicles are bought and sold at auction every year.
07/27/2008	Online Listing	Vehicle offered for sale

<b>Owne</b> Purcha	e <b>r 2</b> ased: 2008		Personal Vehic
Date	Mileage	Source	Comments
08/20/200	08 17,094	Maryland Motor Vehicle Dept. Owings, MD Title #39706677	<b>Registration issued or renewed</b> -Title or registration issued -New owner reported -Loan or lien reported
01/24/200	09	Maryland Inspection Station Prince Frederick, MD	Passed emissions inspection
03/15/200	)9	Virginia Motor Vehicle Dept.	Vehicle purchase reported
03/11/20	10 37,878	Florida Motor Vehicle Dept. Windermere, FL Title #0103977060	Vehicle purchase reported -Title issued or updated -Title or registration issued -Titled or registered as personal vehicle -Loan or lien reported -Registration updated when owner moved the vehicle to a new location -Vehicle color noted as Green
12/12/20	10	Florida Motor Vehicle Dept. Windermere, FL Title #0103977060	<b>Registration issued or renewed</b> -Titled or registered as personal vehicle -Loan or lien reported -Vehicle color noted as Green

2/18

03/28/2011	Florida	Title issued or updated
	Motor Vehicle Dept.	-Titled or registered as personal vehicle
	Windermere, FL	-Loan or lien reported
	Title #0103977060	-Vehicle color noted as Green
12/30/2011	Florida	Registration issued or renewed
	Motor Vehicle Dept.	-Titled or registered as personal vehicle
	Windermere, FL	-Loan or lien reported
	Title #0103977060	-Vehicle color noted as Green
12/28/2012	Florida	Registration issued or renewed
	Motor Vehicle Dept.	<ul> <li>Titled or registered as personal vehicle</li> </ul>
	Windermere, FL	-Loan or lien reported
	Title #0103977060	-Vehicle color noted as Green
04/23/2014	Florida	Registration issued or renewed
	Motor Vehicle Dept.	<ul> <li>Titled or registered as personal vehicle</li> </ul>
	Owings, MD	<ul> <li>Registration updated when owner moved</li> </ul>
	Title #0103977060	the vehicle to a new location
		-Vehicle color noted as Green
06/11/2014	General Motors	Manufacturer Safety recall issued
		-NHTSA# 14V318
		-Recall #15027
		-RECALL 15027 - DRIVER SIDE FRONT SEAT
		BELT CV
		-Status: Remedy Available
		Locate an authorized General Motors dealer to obtain more information about this recall.
		- Learn more about this recall
		hich relates to motor vehicle safety exists in 2004- omatic tensioning system cable in the driver's side
front seat belt retr this occurs, it will If a crash were to	become obvious to the seat occupant	, the result could increase the injury to the driver.
front seat belt retr this occurs, it will If a crash were to Remedy: Dealers a	become obvious to the seat occupant occur with a seat belt in this condition, are to replace the driver side retractor f	immediately. the result could increase the injury to the driver. ree of charge.
front seat belt retr this occurs, it will If a crash were to	become obvious to the seat occupant occur with a seat belt in this condition,	immediately. the result could increase the injury to the driver. ree of charge. Manufacturer recall/service bulletin issued
front seat belt retr this occurs, it will If a crash were to Remedy: Dealers a	become obvious to the seat occupant occur with a seat belt in this condition, are to replace the driver side retractor f	immediately. , the result could increase the injury to the driver. Free of charge. Manufacturer recall/service bulletin issued -Recall #15027
front seat belt retr this occurs, it will If a crash were to Remedy: Dealers a	become obvious to the seat occupant occur with a seat belt in this condition, are to replace the driver side retractor f	immediately. the result could increase the injury to the driver. ree of charge. Manufacturer recall/service bulletin issued
front seat belt retr this occurs, it will If a crash were to Remedy: Dealers a	become obvious to the seat occupant occur with a seat belt in this condition, are to replace the driver side retractor f	immediately. the result could increase the injury to the driver. iree of charge. Manufacturer recall/service bulletin issued -Recall #15027 -RECALL 15027 - DRIVER SIDE FRONT SEAT BELT CV
front seat belt retr this occurs, it will If a crash were to Remedy: Dealers a	become obvious to the seat occupant occur with a seat belt in this condition, are to replace the driver side retractor f	immediately. , the result could increase the injury to the driver. Tree of charge. Manufacturer recall/service bulletin issued -Recall #15027 -RECALL 15027 - DRIVER SIDE FRONT SEAT
front seat belt retr this occurs, it will If a crash were to Remedy: Dealers a	become obvious to the seat occupant occur with a seat belt in this condition, are to replace the driver side retractor f	immediately. , the result could increase the injury to the driver. Free of charge. Manufacturer recall/service bulletin issued -Recall #15027 -RECALL 15027 - DRIVER SIDE FRONT SEAT BELT CV Locate an authorized Saab Warranty Service Provider to obtain more information about
front seat belt retr this occurs, it will If a crash were to Remedy: Dealers a 06/24/2014 Description: Gener	become obvious to the seat occupant occur with a seat belt in this condition, are to replace the driver side retractor f Saab Cars North America ral Motors has decided that a defect w	immediately. the result could increase the injury to the driver. free of charge. Manufacturer recall/service bulletin issued -Recall #15027 -RECALL 15027 - DRIVER SIDE FRONT SEAT BELT CV Locate an authorized Saab Warranty Service Provider to obtain more information about this recall

If a crash were to occur with a seat belt in this condition, the result could increase the injury to the driver.

Remedy: Dealers are to replace the driver side retractor free of charge.

06/27/2014			
	50,508	Virginia Inspection Station	Failed safety inspection
06/30/2014		Virginia Inspection Station	Passed safety inspection
06/30/2014	51,700	Virginia	Title issued or updated
		Motor Vehicle Dept.	-Title or registration issued
		Herndon, VA	-Registration updated when owner moved the vehicle to a new location
)5/06/2015		Virginia Motor Vehicle Dept. Herndon, VA	Registration issued or renewed
0/24/2015	51,892	Virginia Inspection Station	Passed safety inspection
05/11/2016		General Motors	Manufacturer Safety recall issued -NHTSA# 16V063 -Recall #15043
			-SAAB TAKATA AIRBAGS HAH AREA
			-Status: Remedy Available
			Locate an authorized General Motors dealer to obtain more information about this recall.
			- Learn more about this recall
lead to overa excessive in rupturing up In the event may result in Remedy: Dea	aggressive ternal press on deploym of an inflate n injury or d alers will re	combustion in the event of an sure when the air bag is deploy nent. or rupture, metal fragments co eath to vehicle occupants.	air bag deployment. This condition could create yed, which could result in the body of the inflator uld pass through the air bag cushion material, which
lead to overa excessive in rupturing up In the event of may result in Remedy: Dea free of charg	aggressive ternal press on deploym of an inflate n injury or d alers will re	combustion in the event of an sure when the air bag is deploy nent. or rupture, metal fragments co eath to vehicle occupants.	air bag deployment. This condition could create yed, which could result in the body of the inflator uld pass through the air bag cushion material, which
lead to overa excessive in rupturing up In the event may result in	aggressive ternal press on deploym of an inflate n injury or d alers will re ge.	combustion in the event of an sure when the air bag is deploy nent. or rupture, metal fragments co eath to vehicle occupants. place the driver airbag asseml Virginia Inspection Station	yed, which could result in the body of the inflator ould pass through the air bag cushion material, which oly on Saab 9-3 and 9-5 vehicles subject to this recall,

2/18/2020

CARFAX Vehicle History Report for this 2006 SAAB 9-3: YS3FD79Y966005518

04/05/2018	53,363	Virginio	Depend sofety inspection
04/05/2018	55,505	Virginia Inspection Station	Passed safety inspection
06/23/2018		Virginia Inspection Station Sterling, VA	Passed emissions inspection
06/23/2018		Virginia Motor Vehicle Dept. Herndon, VA	Registration issued or renewed
4/23/2019	55,306	Virginia Inspection Station	Passed safety inspection

Have Questions? Consumers, please visit our Help Center at www.carfax.com . Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com .



#### First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

#### **Manufacturer Recall**

Automobile manufacturers issue recall notices to inform owners of car defects that have come to the manufacturer's attention. Recalls also suggest improvements that can be made to improve the safety of a particular vehicle. Most manufacturer recalls can be repaired at no cost to you.

#### **New Owner Reported**

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

### **Ownership History**

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

#### **Title Issued**

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.



facebook.com/CARFAX





CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAXå°

æ<sup>1</sup>/<sub>4</sub> 2020 CARFAX, Inc., a unit of IHS Markit. All rights reserved. Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838. 2/18/20 2:29:15 PM (CST) I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2006 SAAB 9-3 vehicle (VIN: YS3FD79Y966005518), which is based on information supplied to CARFAX and available as of 2/18/20 at 3:29 PM (EST).

**Customer Signature** 

Date

**Dealer Signature** 

Date