

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
201109
DATE
6/20/2013

Klaas Kwant  
4150 Grand River  
Grand Rapids, MI  
49525

Service For: <b>1990 Saab 900 SPG</b> <b>VIN# YS3AL35L1L3001234</b>		
<b>MILEAGE 180531</b>	Lic #	BZC 6437

TERMS	Rep	MI Reg#
Due at invoice	AR	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
72161	1	Oil Filter	4.71	4.71T
3370	4.5	5W30 Synthetic Blend	4.43	19.94T
*1		Supply Fee	2.10	2.10T
Kent/1V21XOTN9AYERS	0.3	Change oil and filter	50.00	15.00
Kent/1V21XOTN9AYERS	1.1	Open hatch and adjust mechanism for proper function. Also attempted to adjust hood latch but need radiator support pulled forward to allow more adjustment.	77.50	85.25
Kent/1V21XOTN9AYERS	0.5	Wired in fog lights and replaced blown fuse. However light still does not function. NOTE: Need to reschedule for right upper control arm bushings and e brake repair.	77.50	38.75
		Michigan sales tax	6.00%	1.61

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$167.36
--	--------------	----------

ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
201159
DATE
7/11/2013

**Klass Kwant**  
**Candace Cowling**  
**4150 Grand River**  
**Grand Rapids, MI 49525**

Service For: <b>1990 Saab 900 SPG</b> VIN# YS3AL35L1L3001234		
<b>MILEAGE 186749</b>	Lic #	BZC 6437

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
Kent/1V21XOTN9AYERS		Primary damage to right front corner, Pull frame and replace radiator support and bumper, Install head light, marker and grill (customer supplied) and repair hood. Michigan sales tax	2,300.00	2,300.00
			6.00%	0.00

All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$2,300.00
---	--------------	------------

**ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.**

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
 MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
 Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
201403
DATE
12/23/2013

**Klaas Kwant**  
**4150 Grand River**  
**Grand Rapids, MI**  
**49525**

Service For: <b>1990 Saab 900 SPG</b> <b>VIN# YS3AL35L1L3001234</b>
<b>MILEAGE 184490</b> Lic #      BZC 6437

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
3370	4.5	5W30 Synthetic Blend	4.43	19.94T
72161	1	Oil Filter	4.71	4.71T
Parts	2	12-20 Zebra Clamp	1.24	2.48T
3374	0.4	ATF	4.36	1.74T
AF1100	0.75	Antifreeze	18.33	13.75T
Fluid	1	Washer Fluid	2.99	2.99T
7228-180	1	Thermostat	17.83	17.83T
*1	1	Supply Fee	6.42	6.42T
Kent/1V21XOTN9AYERS	1.4	Replace thermostat and fill coolant	77.50	108.50
Kent/1V21XOTN9AYERS	0.3	Change oil and filter	77.50	23.25
Kent/1V21XOTN9AYERS	0.7	Cut Power steering return hose crimp clamp and replace with zebra clamps.	77.50	54.25
		Michigan sales tax	6.00%	4.19

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$260.05
--	--------------	----------

ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
 MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
 Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #

202190

DATE

6/2/2015

**Klaas Kwant**  
**4150 Grand River**  
**Grand Rapids, MI**  
**49525**

Service For: <b>1990 Saab 900 SPG</b> <b>VIN# YS3AL35L1L3001234</b>		
<b>MILEAGE 197804</b>	Lic #	BZC 6437

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
0261974	1	Antenna mast	29.40	29.40T
R12	1.1	R12	63.50	69.85T
*1		Supply Fee	9.21	9.21T
Kent/1V21XOTN9AYERS	1.4	Remove driver seat hinge and repair	77.50	108.50
Kent/1V21XOTN9AYERS	0.9	Diagnose engine squeal on boost. Found air port on throttle body had come loose, Reattached and secured with sleeve locker	77.50	69.75
Kent/1V21XOTN9AYERS	0.75	Remove antenna motor and installed new mast.	77.50	58.13
Kent/1V21XOTN9AYERS	0.8	Test AC and found slightly low. Added freon. next service will likely need a retrofit. R12 is nearly impossible to get at any price.	77.50	62.00
		Michigan sales tax	6.00%	6.51

\*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.

**Total**

\$413.35

**ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.**

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
 MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
 Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #

202481

DATE

12/31/2015

**Klaas Kwant**  
**4150 Grand River**  
**Grand Rapids, MI**  
**49525**

Service For: <b>1990 Saab 900 SPG</b> <b>VIN# YS3AL35L1L3001234</b>		
<b>MILEAGE 201299</b>	Lic #	BZC 6437

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
72161	1	Oil Filter	4.71	4.71T
5954	4.5	Semi Synthetic 5W30 Motor Oil	4.47	20.12T
AF1100	0.5	Antifreeze	18.33	9.17T
443407625	1	Wheel Bearing	114.30	114.30T
26-550	1	Battery	91.85	91.85T
*1		Supply Fee	6.44	6.44T
Kent/1V21XOTN9AYERS	2	Diagnose drive train noise and replace right front wheel bearing	77.50	155.00
Kent/1V21XOTN9AYERS	0.4	Change oil and filter, Toped off fluids	77.50	31.00
Kent/1V21XOTN9AYERS	0.5	Adjust ebrake	77.50	38.75
Kent/1V21XOTN9AYERS	0.6	Test Battery, charging and starting and system and replace battery	77.50	46.50
		Michigan sales tax	6.00%	14.80

\*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.

**Total**

\$532.64

**ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.**

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:

MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910

Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
202921
DATE
9/6/2016

Klaas Kwant  
4150 Grand River  
Grand Rapids, MI  
49525

Service For: <b>1990 Saab 900 SPG</b> <b>VIN# YS3AL35L1L3001234</b>		
<b>MILEAGE 206141</b>	Lic #	BZC 6437

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
03010	1	Distributor cap	15.66	15.66T
04168	1	Ignition Rotor	23.99	23.99T
3010	4	Denso Spark Plug	3.25	13.00T
8962656	1	Sway Bar Bushing/Bracket	23.03	23.03T
30519423	1	Sway Bar Bushing/Bracket	23.03	23.03T
7545668	1	Front Engine Mount	116.15	116.15T
FW109	1	Front Wheel Bearing	83.06	83.06T
*1		Supply Fee	7.91	7.91T
Kent/1V21XOTN9AYERS	2.8	Replace ignition distributor with customer supplied part. Had to merge two distributors to get one good one.	84.70	237.16
Kent/1V21XOTN9AYERS	1.7	Replace front engine mount	84.70	143.99
Kent/1V21XOTN9AYERS	1.7	Replace front left wheel bearing	84.70	143.99
		Michigan sales tax	6.00%	18.35

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$849.32
--	--------------	----------

ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
202921
DATE
9/6/2016

Klaas Kwant  
4150 Grand River  
Grand Rapids, MI  
49525

Service For: <b>1990 Saab 900 SPG</b> <b>VIN# YS3AL35L1L3001234</b>		
<b>MILEAGE 206141</b>	Lic #	BZC 6437

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
03010	1	Distributor cap	15.66	15.66T
04168	1	Ignition Rotor	23.99	23.99T
3010	4	Denso Spark Plug	3.25	13.00T
8962656	1	Sway Bar Bushing/Bracket	23.03	23.03T
30519423	1	Sway Bar Bushing/Bracket	23.03	23.03T
7545668	1	Front Engine Mount	116.15	116.15T
FW109	1	Front Wheel Bearing	83.06	83.06T
*1		Supply Fee	7.91	7.91T
Kent/1V21XOTN9AYERS	2.8	Replace ignition distributor with customer supplied part. Had to merge two distributors to get one good one.	84.70	237.16
Kent/1V21XOTN9AYERS	1.7	Replace front engine mount	84.70	143.99
Kent/1V21XOTN9AYERS	1.7	Replace front left wheel bearing	84.70	143.99
		Michigan sales tax	6.00%	18.35

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$849.32
--	--------------	----------

ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
202963
DATE
10/4/2016

Klaas Kwant  
4150 Grand River  
Grand Rapids, MI  
49525

Service For: <b>1990 Saab 900 SPG</b> <b>VIN# YS3AL35L1L3001234</b>
--

<b>MILEAGE 207100</b>	Lic #	BZC 6437
-----------------------	-------	----------

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
8819831	1	Head Gasket Set	181.25	181.25T
13x1184	1	A/C Comp belt	23.99	23.99T
MG23	1	Gasket	5.39	5.39T
7228-180	1	Thermostat	22.08	22.08T
5955	4.5	5W30 Synthetic Motor Oil	7.21	32.45T
72161	1	Oil Filter	4.71	4.71T
AF1100	1.5	Antifreeze	18.33	27.50T
*1		Supply Fee	8.14	8.14T
Kent/1V21XOTN9AYERS	9.8	Diagnose coolant loss, Exhaust smoke. Remove and replaced cylinder head gasket. Checked head surface (No warpage) also replace ac compressor belt.	84.70	830.06
		Michigan sales tax	6.00%	18.33

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$1,153.90
--	--------------	------------

ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
Service Performed by:



# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
203090
DATE
1/14/2017

Klaas Kwant  
4150 Grand River  
Grand Rapids, MI  
49525

Service For: <b>1990 Saab 900 SPG</b> <b>VIN# YS3AL35L1L3001234</b>
--

<b>MILEAGE 107827</b>	Lic #	BZC 6437
-----------------------	-------	----------

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
Parts	1	ABS master cylinder and module assembly (USE)	300.00	300.00T
DOT4	3	Brake Fluid	4.50	13.50T
*1		Supply Fee	12.61	12.61T
Kent/1V21XOTN9AYERS	2.3	Diagnose sticking brakes, tried new fluid and bleeding but ended up replacing assembly with used and bleeding system.	84.70	194.81
		Michigan sales tax	6.00%	19.57

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$540.49
--	--------------	----------

ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
203104
DATE
1/25/2017

Klaas Kwant  
4150 Grand River  
Grand Rapids, MI  
49525

Service For: <b>1990 Saab 900 SPG</b> VIN# YS3AL35L1L3001234		
<b>MILEAGE 107899</b>	Lic #	BZC 6437

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
CL2001	1	Ind Clamp	2.97	2.97T
DOT4	1	Brake Fluid	4.50	4.50T
*1		Supply Fee	2.10	2.10T
Kent/1V21XOTN9AYERS	1	Replace exhaust clamp and flush and bleed clutch system	84.70	84.70
		Michigan sales tax	6.00%	0.57

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$94.84
--	--------------	---------

ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
203127
DATE
2/7/2017

Klaas Kwant  
4150 Grand River  
Grand Rapids, MI  
49525

Service For: <b>1990 Saab 900 SPG</b> VIN# YS3AL35L1L3001234		
<b>MILEAGE 209631</b>	Lic #	DZC 6437

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
*1 Kent/1V21XOTN9AYERS	1.2	<b>Supply Fee</b> <b>Diagnose oil leak and seal distributor shaft, Also snugged up distributor connection for intermittent stall. Plugged leak at throttle body and tested AC. If problem persist it will need relay. Last issue was a pressure sensor connection which was tightened.</b> <b>Michigan sales tax</b>	3.91 84.70  6.00%	3.91T 101.64  0.23

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$105.78
--	--------------	----------

ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
203246
DATE
4/20/2017

Klaas Kwant  
4150 Grand River  
Grand Rapids, MI  
49525

Service For: <b>1990 Saab 900 SPG</b> <b>VIN# YS3AL35L1L3001234</b>		
<b>MILEAGE 209852</b>	Lic #	DZC 6437

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
4776308	1	Clutch Slave Cylinder	121.58	121.58T
DOT4	0.5	Brake Fluid	4.50	2.25T
*1		Supply Fee	4.91	4.91T
Kent/1V21XOTN9AYERS	3	Diagnose clutch failure and replace slave cylinder. NOTE: Clutch was in good condition not requiring replacement at this time.	84.70	254.10
		Michigan sales tax	6.00%	7.72

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$390.56
--	--------------	----------

ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
203573
DATE
10/31/2017

**Klass Kwant**  
**Candace Cowling**  
**4150 Grand River**  
**Grand Rapids, MI 49525**

Service For:	<b>1990 Saab 900 SPG</b> <b>VIN# YS3AL35L1L3001234</b>
<b>MILEAGE</b>	Lic # BZc6437

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
AF1100	0.7	Antifreeze	18.33	12.83T
*1		Supply Fee	3.62	3.62T
Kent/1V21XOTN9AYERS	0.8	Remove and reset thermostat and disable locking function of fail safe stat	84.70	67.76
		Michigan sales tax	6.00%	0.99

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$85.20
--	--------------	---------

**ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.**

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
 MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
 Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
203657
DATE
12/28/2017

**Klaas Kwant**  
**4150 Grand River**  
**Grand Rapids, MI**  
**49525**

Service For: <b>1990 Saab 900 SPG</b> <b>VIN# YS3AL35L1L3001234</b>		
<b>MILEAGE 215134</b>	Lic #	BZC 6437

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
9144445M	1	Oil Filter	5.43	5.43T
5955	4.5	5W30 Synthetic Motor Oil	7.21	32.45T
8781304	1	Clutch Kit	351.54	351.54T
55557240	1	Engine seal	35.47	35.47T
*1		Supply Fee	13.67	13.67T
Kent/1V21XOTN9AYERS	4.1	Replace rear main seal, Remove and reseal rear engine cover. Replaced clutch and pressure plate at same time.	84.70	347.27
Kent/1V21XOTN9AYERS	0.3	Change oil and filter	84.70	25.41
		Michigan sales tax	6.00%	26.31

\*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.

**Total**

\$837.55

**ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.**

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
 MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
 Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
203905
DATE
6/5/2018

**Klaas Kwant**  
**4150 Grand River**  
**Grand Rapids, MI**  
**49525**

Service For: <b>1990 Saab 900 SPG</b> VIN# YS3AL35L1L3001234		
<b>MILEAGE 218582</b>	Lic #	BZC 6437

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
5466842	1	Pipe (Starla)	44.18	44.18T
8817900	1	Water Pump	75.40	75.40T
8993628	1	Axle Boot Kit	31.75	31.75T
8993312	2	Ball Joint	55.67	111.34T
4024121	1	Gasket	9.61	9.61T
250-065	1	Exhaust Clamp	8.46	8.46T
*1		Supply Fee	10.61	10.61T
Kent/1V21XOTN9AYERS	1.1	Replace mid pipe (Welded new metal to mid muffler (Rusted)	84.70	93.17
Kent/1V21XOTN9AYERS	1.9	Remove and replace water pump and adjust belts	84.70	160.93
Kent/1V21XOTN9AYERS	2.8	Replace both right ball joints and axle boot. Added grease to inner joint as well	84.70	237.16
Kent/1V21XOTN9AYERS	1	Smoke test and seal vacuum leaks. Also found leaking (Cracked) Air boot on inlet side of turbo	84.70	84.70
		Michigan sales tax	6.00%	17.48

12 Month 12K Mile Parts and labor warrantee. Warrantee does not cover neglect or abuse.	<b>Total</b>	\$884.79
---	--------------	----------

**ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.**

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
 MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
 Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
203957
DATE
7/13/2018

**Klaas Kwant**  
**4150 Grand River**  
**Grand Rapids, MI**  
**49525**

Service For: <b>1990 Saab 900 SPG</b> <b>VIN# YS3AL35L1L3001234</b>
<b>MILEAGE 219556</b> Lic #      BZC 6437

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
8817900	1	<b>Water Pump</b>	75.40	75.40
93185052	1	<b>Accessory Drive Belt (SET)</b>	13.28	13.28
AF1100	1	<b>Antifreeze</b>	18.33	18.33
10*825	1	<b>Drive Belt</b>	8.31	8.31
Kent/1V21XOTN9AYERS	1.9	<b>Replace water pump, pulley and belts along with power steering belt.</b>	84.70	160.93
Credit		<b>Water pump warrantee</b>	-276.25	-276.25
*1		<b>Supply Fee</b>	3.92	3.92T
Kent/1V21XOTN9AYERS	0.8	<b>Diagnose AC and repair relay (Should get a new one if fails again)</b>	84.70	67.76
		<b>Michigan sales tax</b>	6.00%	0.24

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$71.92
--	--------------	---------

**ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.**

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
 MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
 Service Performed by:



# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
204195
DATE
11/28/2018

**Klaas Kwant**  
**4150 Grand River**  
**Grand Rapids, MI**  
**49525**

Service For: <b>1990 Saab 900 SPG</b> <b>VIN# YS3AL35L1L3001234</b>		
<b>MILEAGE BZC 6437</b>	Lic #	222512

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
9365404	1	<b>Exh Hanger</b>	3.16	3.16T
255-721	2	<b>Rubber Mount</b>	5.03	10.06T
215-755	1	<b>Silencer</b>	148.98	148.98T
72161	1	<b>Oil Filter</b>	4.71	4.71T
5955	5	<b>5W30 Synthetic Motor Oil</b>	7.21	36.05T
*1		<b>Supply Fee</b>	3.61	3.61T
Kent/1V21XOTN9AYERS	0.3	<b>Change oil and filter, Also topped off gear box.</b>	84.70	25.41
Kent/1V21XOTN9AYERS	1	<b>Replace mid muffler and tail pipe</b>	84.70	84.70
Kent/1V21XOTN9AYERS	0.3	<b>Remove after mkt seal and adjust door</b>	84.70	25.41
Kent/1V21XOTN9AYERS	1.2	<b>Diagnose horn issue and correct contact point under steering wheel.</b>	84.70	101.64
		<b>Gave 49 series battery to test in candies car.</b>		
		<b>Michigan sales tax</b>	6.00%	12.39

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$456.12
--	--------------	----------

**ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.**

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
 MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
 Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
204441
DATE
5/14/2019

Klaas Kwant  
4150 Grand River  
Grand Rapids, MI  
49525

Service For: <b>1990 Saab 900 SPG</b> <b>VIN# YS3AL35L1L3001234</b>		
<b>MILEAGE 225945</b>	Lic #	BZC 6437

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
343023	2	Shock (KYB)	61.51	123.02T
8970717	2	Brake Rotor (Brembo)	48.77	97.54T
04168	1	Ignition Rotor	20.91	20.91T
32017602	1	Brake Pad Set (TEX)	62.62	62.62T
03010	1	Distributor cap	24.63	24.63T
8817314	1	Ignition Wire Set	73.59	73.59T
AF1100	0.8	Antifreeze	18.33	14.66T
DOT4	0.5	Brake Fluid	4.50	2.25T
*1	1	Supply Fee	5.12	5.12T
Kent/1V21XOTN9AYERS	2	Replace rear brake pads and rotors, Clean and lube brake hardware and bleed	84.70	169.40
Kent/1V21XOTN9AYERS	1.2	Replace distributor cap, rotors and wire set	84.70	101.64
Kent/1V21XOTN9AYERS	1.2	Diagnose poor ride, Replace front shocks. Left shock stuck! Also right lower mounting point threads needed to be taped	84.70	101.64
		Michigan sales tax	6.00%	25.46

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$822.48
--	--------------	----------

ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
204665
DATE
9/16/2019

Klaas Kwant  
4150 Grand River  
Grand Rapids, MI  
49525

Service For: <b>1990 Saab 900 SPG</b> <b>VIN# YS3AL35L1L3001234</b>
--

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

MILEAGE	Lic #
---------	-------

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
B12G	1	Ground Strap	17.89	17.89T
*1		Supply Fee	8.31	8.31T
Kent/1V21XOTN9AYERS	1.6	Diagnose charging system issue and replace ground strap on alternator	84.70	135.52
		Michigan sales tax	6.00%	1.57

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$163.29
--	--------------	----------

ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
205656
DATE
6/7/2021

Klaas Kwant  
4150 Grand River  
Grand Rapids, MI  
49525

Service For: <b>1990 Saab 900 SPG</b> <b>VIN: YS3AL35L1L3001234</b>		
<b>MILEAGE 238930</b>	Lic #	EFD 3646

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
Parts	1	32019063 Ignition Lock Cyl	182.89	182.89T
Misc.		Shop Supplies	2.10	2.10T
		Michigan sales tax	6.00%	11.10

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$196.09
--	--------------	----------

ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
206111
DATE
3/7/2022

**Klass Kwant**  
**Candace Cowling**  
**4150 Grand River**  
**Grand Rapids, MI 49525**

Service For: <b>1990 Saab 900 SPG</b> <b>VIN: YS3AL35L1L3001234</b>
--

<b>MILEAGE 243735</b>	Lic #	EFD 3646
-----------------------	-------	----------

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
Parts	1	72161 Oil Filter	9.17	9.17T
Parts	4.5	5W30 Synth Motor Oil	8.21	36.95T
Parts	1	32021864, Ball Joint	71.88	71.88T
Parts	1	9189564 PCV Check Valve	28.40	28.40T
Misc.		Shop Supplies	6.31	6.31T
Kent/1V21XOTN9AYERS	0.4	Change oil and filter	94.70	37.88
Kent/1V21XOTN9AYERS	1.1	Remove damaged liner in antenna and install new mast	94.70	104.17
Kent/1V21XOTN9AYERS	1.6	Check suspension and replace right lower ball joint	94.70	151.52
		Michigan sales tax	6.00%	9.16

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$455.44
--	--------------	----------

**ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.**

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
 MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
 Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
206388
DATE
7/29/2022

**Klaas Kwant**  
**4150 Grand River**  
**Grand Rapids, MI**  
**49525**

Service For: <b>1990 Saab 900 SPG</b> <b>VIN: YS3AL35L1L3001234</b>
--

<b>MILEAGE 246262</b>	Lic #	EFD 3646
-----------------------	-------	----------

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
Parts	1	32019204 Clutch slave cylinder	159.75	159.75T
Parts	1	8781304 Clutch kit	369.24	369.24T
Parts	1	8721995 T/O Bearing	29.10	29.10T
Parts	1	SR32X Starter	211.00	211.00T
Fluid	0.75	AF1100 Coolant	27.89	20.92T
Misc.		Shop Supplies	9.24	9.24T
Kent/1V21XOTN9AYERS	3.6	Diagnose clutch failure and replace disk, Pressure plate, Throwout bearing and slave cylinder	94.70	340.92
Kent/1V21XOTN9AYERS	2.3	Diagnose no crank, Tested starter and replaced, Also cleaned and lubed ignition switch (Sticking likely causing starter failure)	94.70	217.81
		Michigan sales tax	6.00%	47.96

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$1,405.94
--	--------------	------------

ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
 MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
 Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
206538
DATE
10/24/2022

Klaas Kwant  
4150 Grand River  
Grand Rapids, MI  
49525

Service For: <b>1990 Saab 900 SPG</b> <b>VIN: YS3AL35L1L3001234</b>
--

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

MILEAGE	Lic #
---------	-------

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
Misc. Kent/1V21XOTN9AYERS	0.8	<b>Shop Supplies</b>	2.10	2.10T
		<b>Diagnose poor start and idle, Correct air leak at blowoff valve.</b>	94.70	75.76
		<b>Michigan sales tax</b>	6.00%	0.13

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$77.99
--	--------------	---------

ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #

206741

DATE

2/14/2023

**Klaas Kwant**  
**4150 Grand River**  
**Grand Rapids, MI**  
**49525**

Service For: <b>1990 Saab 900 SPG</b> <b>VIN: YS3AL35L1L3001234</b>		
<b>MILEAGE</b>	Lic #	EFD 3646

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
Parts	1	17-493 Front pads	89.99	89.99T
Parts	1	17465 Drive belt	15.55	15.55T
Parts	1	9189564 PCV Valve	30.92	30.92T
Misc.		Shop Supplies	3.09	3.09T
Kent/1V21XOTN9AYERS	0.9	Replace front pads	107.40	96.66
Kent/1V21XOTN9AYERS	1.4	Smoke intake system and repair vacuum storage leak and install inline check valve	107.40	150.36
Kent/1V21XOTN9AYERS	0.6	Replace drive belt for AC	107.40	64.44
		Michigan sales tax	6.00%	8.37

\*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.

**Total**

\$459.38

**ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.**

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
 MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
 Service Performed by:



# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
206961
DATE
6/21/2023

Klaas Kwant  
4150 Grand River  
Grand Rapids, MI  
49525

Service For: <b>1990 Saab 900 SPG</b> <b>VIN: YS3AL35L1L3001234</b>
<b>MILEAGE 251865</b> Lic #      EFD 3646

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
Misc. Kent/1V21XOTN9AYERS	1.5	<b>Shop Supplies</b> <b>Diagnose AC failure and repair AC relay. NOTE: There was melted plastic at relay.</b> <b>Michigan sales tax</b>	2.10 107.40 6.00%	2.10T 161.10 0.13

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$163.33
--	--------------	----------

ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
Service Performed by:

# Automotive Emporium, Inc.

3716 South Division

Wyoming, MI 49548-3250

PH:(616)452-3024

Fax(616)452-3152

Invoice #
207448
DATE
4/30/2024

Klaas Kwant  
4150 Grand River  
Grand Rapids, MI  
49525

Service For: <b>1990 Saab 900 SPG</b> <b>VIN: YS3AL35L1L3001234</b>		
<b>MILEAGE 257275</b>	Lic #	EFD 3646

TERMS	Rep	MI Reg#
Due at invoice	KA	F142534

Item number	QTY	DESCRIPTION OF SERVICE	RATE	AMOUNT
Parts	1	72161 Bosch Oil Filter	10.30	10.30T
Fluid	4.2	5W30 Full synthetic motor oil	8.21	34.48T
Misc.		Shop Supplies	2.94	2.94T
Kent/1V21XOTN9AYERS	0.5	Change oil and filter.	107.40	53.70
		Photo Underside		
		Michigan sales tax	6.00%	2.86

*All warranty work must be performed in our shop & cannot exceed the original cost of repairs.	<b>Total</b>	\$104.28
--	--------------	----------

ALL PARTS ARE NEW UNLESS OTHER WISE STATED YOU ARE ENTITLED BY LAW TO THE RETURN OF ALL PARTS REPLACED EXCEPT THOSE WHICH ARE TOO HEAVY OR LARGE, AND THOSE REQUIRED TO BE SENT BACK TO THE MANUFACTURER OR DISTRIBUTOR BECAUSE OF WARRANTY WORK OR AN EXCHANGE AGREEMENT. YOU ARE ENTITLED TO INSPECT THE PARTS WHICH CANNOT BE RETURNED TO YOU. Automotive Emporium is not responsible for loss or damage to vehicle, in case of fire theft or other casues beyond their control. I hereby authorize repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. I have read and understand the above terms.

Authorized by: \_\_\_\_\_

Repairs and parts were furnished in compliance with MI Auto Repair Act (P.A.3001)

Representative:  
MI Certification Number M179087 & ASE#1V21XOTN9AYERS or M179910  
Service Performed by: